

# Oil Field Environmental Incident Summary

**Incident:** 20141207201533      **Date/Time of Notice:** 12/07/2014 20:15

**Responsible Party:** Hiland Crude LLC

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** MARLENE 2-3H1

**Field Name:** STONEVIEW

**Well File #:** 26693

**Date Incident:** 12/7/2014      **Time Incident:** 08:30

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 159

**Rng:** 95

**Sec:** 3

**Qtr:**

**Location Description:**

**Submitted By:** Austin Schneider

**Received By:**

**Contact Person:** Steve Jensen  
302 N Independence  
Enid, OK 73701

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	5	Barrels			5	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 10/14/2016

**Clean Up Concluded:** 12/7/2014

**Risk Evaluation:**

None

**Areal Extent:**

Small area was impacted by a fine mist sprays (5-10) gallons.

**Potential Environmental Impacts:**

Impact limited to soil inside the lined secondary containment and small amount of snow outside the secondary containment

**Action Taken or Planned:**

Response Team Absorbent & Safety Solution on location. Soil inside the lined secondary will be removed via vacuum truck. Snow with fine mist spray will be removed from location.

**Wastes Disposal Location:** Contaminated soil from inside the secondary containment and small amount of snow will be disposed at Prairie Disposal.

**Agencies Involved:****Updates**

---

**Date:** 12/8/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to an on-location valve/piping leak during apparent loading/sale operations, remained on location according to the report. NDIC retains oversight.